	Туре	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	0	10/712066	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 14:07
2	BRS	L2	4573		US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 14:16
3	BRS	L3	1939	waveguide)) near11 coupl\$4 same (fibers fibres waveguides (second adj1	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 15:38
4	BRS	L4	2	adj2 ((thermal\$3 adj1	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 14:24
5	BRS	L5	0	film\$3 jaket\$3 coat\$4 ferrule\$1)) near7 negative adj2 ((thermal\$3 adj1	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 14:25

	Comments	Error Definition	Err
1			
2			
3		·.	
4			
5			

	Туре	L#	Hits	Search Text	DBs	Time Stamp
6	BRS	L6	2	(ceramic\$2 near7 (tape film\$3 jaket\$3 coat\$4 ferrule\$1)) near7 negative adj2 ((thermal\$3 adj1 expan\$5) cte)	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 14:29
7	BRS	L7	38	(ceramic\$2 near7 (material\$1 tap\$3 film\$3 jaket\$3 coat\$4 ferrule\$1)) near4 negative adj2 ((thermal\$3 adj1 expan\$5) cte)	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 14:41
8	BRS	L8	0	(ceramic\$2 near7 (material\$1 tap\$3 film\$3 jaket\$3 coat\$4 ferrule\$1)) near4 negative adj2 ((thermal\$3 adj1 expan\$5) cte) same coupl\$4	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 14:30
9	BRS	L9		(ceramic\$2 near7 (material\$1 tap\$3 film\$3 jaket\$3 coat\$4 ferrule\$1)) near4 negative adj2 ((thermal\$3 adj1 expan\$5) cte) same ferrule\$1	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 14:42
10	BRS	L10		(ceramic\$2 near7 (material\$1 tap\$3 film\$3 jaket\$3 coat\$4 ferrule\$1)) near4 negative adj2 ((thermal\$3 adj1 expan\$5) cte) same jaket\$3	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 14:42

	Comments	Error Definition	Err
6	·		
7			
8			
9.	·		
10			

	Туре	L #	Hits	Search Text	DBs	Time Stamp
11	BRS	L11	2	(ceramic\$2 near7 (material\$1 tap\$3 film\$3 jaket\$3 coat\$4 ferrule\$1))	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 14:44
12	BRS	L12		(ceramic\$2 near/ (material\$1 tap\$3 film\$3 jaket\$3 coat\$4 ferrule\$1)) near4 negative adj2 ((thermal\$3 adj1 expan\$5)	IH: D( ) •	2005/06/15 14:44
13	BRS	L13	3735	coupler\$1 near12 fus\$5	IH: D( ) •	2005/06/15 14:50
14	BRS	L14		(ferrule tub\$3 jacket\$3 tap\$3) near7 negative adj2 ((thermal\$3 adj1 expan\$5)	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 14:53
15	BRS	L15	0	(ferrule tub\$3 jacket\$3 tap\$3) near7 negative adj2 ((thermal\$3 adj1 expan\$5) cte) same (coupl\$4 fus\$4)	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/06/15 14:54

,	Comments	Error Definition	Err ors
11	·		·
12			
13			
14			
15			·

	Туре	L #	Hits	Search Text	DBs	Time Stamp
16	BRS	L16	3	(ferrule\$1 tub\$4 jacket\$3 tap\$3) near7 negative near5 ((thermal\$3 adj1 expan\$5) cte) same (coupl\$4 fus\$4)		2005/06/15 15:07
17	BRS	L17	52 .	(ferrule\$1 tub\$4 jacket\$3 tap\$3) near11 negative near5 ((thermal\$3 adj1 expan\$5) cte)	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 17:34
18	BRS	L18	0	3 and 17	IH: D( ) •	2005/06/15 15:08
19	BRS	L19	29	17 and coupl\$3	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 15:09
20	BRS	L20	19	17 and coupl\$3 same (ferrule\$1 tub\$4 jacket\$3 tap\$3)	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 15:10

	Comments	Error Definition	Err
16			
17			
18			
19			
20	·		

	Туре	L #	Hits	Search Text	DBs	Time Stamp
21	BRS	L21	5	17 and coupl\$3 same (ferrule\$1 tub\$4 jacket\$3 tap\$3) same (fiber\$1fibr\$1	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 18:01
22	BRS	L22	0	IDPAT / DOGITIVS ( DPATS	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 15:47
23	BRS	L23	1656	(fibers fibres waveguides second adj1 (fiber fibre waveguide)) near7 fus\$4	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 15:48
24	BRS	L24	0	positiv\$3 near5 ((therm\$3 adj1 expan\$4) cte\$1) same (ferrul\$3 tub\$4) near7	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 15:49
25	BRS	L25	123	(fiber\$1 fibre\$1) near7 positiv\$3 near5 ((therm\$3 adj1 expan\$4) cte\$1)	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 15:53

	Comments	Error Definition	Err
			ors
21			
22			÷
23			
24			
25			

	Туре	L #	Hits	Search Text	DBs	Time Stamp
26	BRS	L26		(fiber\$1 fibre\$1 fus\$4 coupl\$3) near7 positiv\$3 near5 ((therm\$3 adj1	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 16:00
27	BRS	L27	I .	(ferrul\$3 tub\$4) near7 (fill\$4 resin\$3 epox\$5 inject\$4) near7 (fus\$3	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 15:55
28	BRS	L28	0	23 and 25 and 26 and 27	IH: P[ ] •	2005/06/15 15:54
29	BRS	L29	142	(fiber\$1 fibre\$1 fus\$4 coupl\$4) near7 positiv\$3 near5 ((therm\$3 adj1 expan\$4) cte\$1)	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 15:55
30	BRS	L30	0	23 and 29 and 26 and 27	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 15:54

	Comments	Error Definition	Err
26			
27			
28	·		
29			·
30		-	

	Туре	L#	Hits	Search Text	DBs	Time Stamp
31	BRS	L31	11	23 and 27	(H: P( ) •	2005/06/15 15:55
32	BRS	L32		31 and (fill\$4 resin\$3 epox\$5 inject\$4) near7 (fus\$3 coupl\$1)	H: D( ) •	2005/06/15 16:17
33	BRS	L33	4	23 and 26	IM: D/ 1 •	2005/06/15 16:00
34	BRS	L34		23 and (fill\$4 resin\$3 epox\$5 inject\$4) near7 (fus\$3 coupl\$1)	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 16:17
35	BRS	L35	54	23 and (fill\$4 resin\$3 epox\$5 inject\$4) near7 (fus\$3 coupl\$1) same coupler\$1		2005/06/15 16:18

	Comments	Error Definition	Err
31			
32			
33			
34	-		
35			

	Туре	L #	Hits	Search Text	DBs	Time Stamp
36	BRS	L36	1111	nears expanss))	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 17:32
37	BRS	L37	3	compensat\$4 near12 therm\$4 negativ\$3)		2005/06/15 16:55
38	BRS	L38	9	compensat\$4 near12 therm\$4 negativ\$3)	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 16:55
39	BRS	L39	7		US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 16:59
40	BRS	L40	6	38 not 36	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 17:02

	Comments	Error Definition	Err
36			
37			·
38		÷	
39			
40			

	Туре	L#	Hits	Search Text	DBs	Time Stamp
41	BRS	L41	70	coupl\$6 same negative near5 ((thermal\$3 adj1 expan\$5) cte)	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/06/15 17:34
42	BRS	L42	10	23 and 41	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 17:47
43	BRS	L43	0	fill\$5) near4 coupl\$4 near5 (equal negative positive zero) near5 ((thermal\$4	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/06/15 18:24
44	BRS	L44	0	fill\$5) near4 coupl\$4 near5 (equal negative positive zero) near5 ((thermal\$4	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/06/15 18:24
45	BRS	L45	0	epox\$5 near5 (coat\$5 fill\$5) near4 (fus\$4 coupl\$4) near5 (equal negative positive zero) near5 ((thermal\$4 near4 expans\$5) cte\$1)	IH: P( ) •	2005/06/15 18:26

	Comments	Error Definition	Err
41			
42			
43			
44		; ;	
45			

	Туре	L #	Hits	Search Text	DBs	Time Stamp
46	BRS	L46		epox\$5 near5 (equal negative positive zero) near5 ((thermal\$4 near4 expans\$5) cte\$1) same coupl\$4	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 18:32
47	BRS	L48 .	2	((thermal\$4 near4 expans\$5)	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/06/15 18:39
48	BRS	L47	7	epox\$5 near5 (zero) near5 ((thermal\$4 near4 expans\$5) cte\$1)	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/06/15 18:42
49	BRS	L49	12		US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 18:42
50	BRS	L50	0	epox\$5 near5 (positive) near5 ((thermal\$4 near4 expans\$5) cte\$1) same	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/15 18:42

	Comments	Error Definition	Err
46			
47			
48			
49		1	
50	·		

	Туре	L #	Hits	Search Text	DBs	Time Stamp
51	BRS	L51	0 .	epox\$5 near5 (positive) near5 ((thermal\$4 near4 expans\$5) cte\$1) same coupl\$3	IH: P( ) •	2005/06/15 18:43
52	BRS	L52	1	epox\$5 near5 (positive) near5 ((thermal\$4 near4 expans\$5) cte\$1) same	IH: P( ) •	2005/06/15 18:43

	Comments	Error Definition	Err
51			
52			